



Window and door heads

Steel lintels



Paint unrendered head

Concrete lintels



A stipple coat such as **weber.render aid** should be used to provide a key to concrete.

Angle bead fixed to facilitate sloping head to form drip at face.

The visual impact of weep holes in the face of the render can be avoided by draining the cavity through the head.